

A Canadian Solar subsidiary



For professional use only

| 1. | T6 CONNECTOR PARTS                    | 3 |
|----|---------------------------------------|---|
| 2. | T6 PRODUCT SPECIFICATIONS             | 3 |
| 3. | T6 INSTALLATION PARAMETERS            | 4 |
| 4. | SAFETY PRECAUTIONS                    | 4 |
| 5. | T6 FIELD TOOLKIT                      | 5 |
| 6. | CONNECTOR & WIRE ASSEMBLY STEPS       | 6 |
| 7. | THE CORRECT CONNECTION                | 8 |
| 8. | DISCONNECTING THE CONNECTORS          | 8 |
|    | AMENDED EDITIONS AND DATES            | 8 |
|    | LIST OF FORBIDDEN CHEMICAL SUBSTANCES | 9 |

# 1. T6 CONNECTOR PARTS



| Item | Part Name                 |
|------|---------------------------|
| 1    | PV Cable                  |
| 2    | Male Pin Contact (-)      |
| 3    | Male Connector (-)        |
| 4    | Female Socket Contact (+) |
| 5    | Female Connector (+)      |

# 2. T6 CONNECTOR SPECIFICATIONS









Male Connector (-)

Male Pin Contact (-)

Female Connector (+)

Female Socket Contact (+)

## ELECTRICAL DATA:

| Connector Specification | T6                         |
|-------------------------|----------------------------|
| Rated Voltage           | IEC 1500 Vpc / UL 1500 Vpc |
|                         | IEC 1000 Vpc / UL 1500 Vpc |
|                         | 41A (4 mm²) / 40A (12 AWG) |
|                         | 48A (4 mm²) / 40A (12 AWG) |
| Rated Current           | 50A (6 mm²) / 55A (10 AWG) |
|                         | 54A (6 mm²) / 55A (10 AWG) |
|                         | 70A 10 mm² / 8 AWG         |
| Contact Resistance      | ≤ 0.25 mΩ                  |
| Pollution Degree        | Class II                   |
| Protection Class        | Class II                   |
| Protection Degree       | IP68                       |
| Fire Resistance         | UL 94-V0                   |
| Temperature Range       | - 40 °C ∼ + 90 °C          |
| Rated Impulse Voltage   | 16 kV                      |

## MECHANICAL DATA:

| T6                  |
|---------------------|
| 12 AWG /10AWG /8AWG |
| Φ 4.0 mm            |
| Copper, Tin-plated  |
| Crimping/Machined   |
| Locking type        |
|                     |

Note: Installation in a free air run with a cable spacing not less than 100% of the largest cable diameter.

## 3. T6 INSTALLATION PARAMETERS

| Article                      | Cable Outside Diameter (OD) | Picture | Required Torque<br>to Lock | Reference Gap     |
|------------------------------|-----------------------------|---------|----------------------------|-------------------|
| Male<br>Connector (-)        | 42                          | gap     | 2.5 N•m ~ 3.5 N•m          | 0.5 ≤ gap ≤ 1.5mm |
| Female<br>Connector (+)      | - 4.3mm - 6.9mm             | gap     | 2.5 N•m ~ 3.5 N•m          | 0.5 ≤ gap ≤ 1.5mm |
| Male<br>Pin Contact (-)      |                             |         |                            |                   |
| Female Socket<br>Contact (+) |                             |         |                            |                   |
| Male<br>Connector (-)        |                             | gap     | 4N•m ~ 5 N.m               | 0 < gap ≤ 0.5mm   |
| Female Connector (+)         |                             |         | 4N•m ~ 5 N.m               | 0 < gap ≤ 0.5mm   |
| Male<br>Pin Contact (-)      |                             |         |                            |                   |
| Female Socket<br>Contact (+) |                             |         |                            |                   |

#### 4. SAFETY PRECAUTIONS

Products must be assembled and installed by qualified personnel, ensuring all safety regulations are followed. For protection against electric shock, please ensure the system is not energized during installation. Do not disconnect under load. Ensure that the AC and the DC sides are both disconnected and the system is not energized before disconnecting.

Use only the tools and components listed in this installation manual. Follow the instructions as stated in this manual. Do not alter or willingly damage the product in anyway.

- Sealing cap must be used on disconnected connectors to prevent dust ingress.
- Connectors are IP68-rated when mated.
- Do not place connectors directly on roof surface.

# • CAUTION1:

The exposure to or direct contact with chemicals or oils of T6 product may cause corrosion, degradation of performance, or cracking of the product, thus such exposure or direct contact should be strictly prohibited during the process of product manufacturing, transportation, installation and application. It is the user's responsibility to validate any chemical that may come into contact with or used in any of the processes mentioned above, to ensure that such chemical will not affect the performance of T6 products.

## • CAUTION 2:

Any T6 or T4 products can be intermated with each other.

## • CAUTION 3:

Interconnection of different connector types/brands with T6 is not allowed.

#### • CAUTION 4:

Recycling and all other types of comparable disassembly of the above mentioned products have to be performed by a qualified waste management company, in compliance with national and local waste management regulations.

# 5. T6 FIELD TOOLKIT



# Wire crimping tool

| Mark   | Riveting Range       |        |
|--------|----------------------|--------|
| 4.0/12 | 4.0 mm <sup>2</sup>  | 12 AWG |
| 6.0/10 | 6.0 mm <sup>2</sup>  | 10 AWG |
| 10.0/8 | 10.0 mm <sup>2</sup> | 8 AWG  |



**Cutting pliers** 



## PARTS INCLUDED IN FIELD TOOLKIT:

## Wire stripper tool

| Туре   | Crimping Range      |        |
|--------|---------------------|--------|
| 2.5/14 | 2.5 mm <sup>2</sup> | 14 AWG |
| 4.0/12 | 4.0 mm <sup>2</sup> | 12 AWG |
| 6.0/10 | 6.0 mm <sup>2</sup> | 10 AWG |



| Type | Crimping Range     |       |
|------|--------------------|-------|
| 10/8 | 10 mm <sup>2</sup> | 8 AWG |







## 6. CONNECTOR & WIRE ASSEMBLY STEPS

STEP 1: VISUAL INSPECTION OF CONNECTOR

#### FEMALE CONNECTOR

a. Sealing ring should fit cleanly in the slot and not be warped or distorted.



- b. The two plastic clasps should be intact.
- c. Female connectors should not be obstructed by foreign objects or water.
- d. Plastic components should not be cracked.
- e. No damage should be visible on the cable.

## MALE CONNECTOR

- a. Male connector should not be obstructed by foreign objects or water.
- b. Plastic components should not be cracked.
- c. No damage should be visible on the cable.



STEP 2: STRIP THE INSULATION OFF THE CABLE

Using the wire stripper tool, remove the insulation from the cable. For 4/6mm² cable, ensure that the stripping length is 7.5 mm, and for 10mm² cable, the length is 9mm, and that the wire strands are not damaged during the process of stripping the insulation.





STEP 3: CRIMP THE CONTACT

## 4/6mm<sup>2</sup> Cable

Place the contact around the bare section of the stripped wire. Crimp the contact using the wire crimping tool. The crimped contact should withstand pull forces of  $\geq$ 310 N.



#### 10mm<sup>2</sup> Cable

Place the contact around the bare section of the stripped wire. Make sure the wire is visible from the hole .Crimp the contact using the wire crimping tool. Crimp position is as shown in the figure.The crimped contact should withstand pull forces of  $\geq$ 380 N.





Correct crimping

Incorrect crimping







STEP 4: INSERT THE CONTACT

Push the crimped contact back into the connector until you hear a click. Lightly pull the wire to ensure the metal components of the connector are engaged.



STEP 5: TIGHTEN THE CABLE GLAND

First, tighten the gland by hand. Then use the disconnect tools to tighten the gland to the connector until it clicks, ensuring that it is locked. When tighteng the male connector, please use aligner available on the disconnect tool in order to ensure the pin is not skewed.



# STEP 6: CONNECTING THE CONNECTORS

Check the appearance of the connectors before connecting them together. The sealing ring should be in the slot with no warping or distortion. The plastic clasps should not be damaged or broken. The connectors should be free of moisture and foreign objects. Plastic parts should not be cracked. Wire s hould not be frayed or damaged. When attaching, insert the connectors into each other until you hear a "click". Once attached, gently pull on the connectors to ensure they are firmly connected and cannot be easily disconnected by hand.




STEP 7: VISUAL INSPECTION OF THE CONNECTION

To check the connection, ensure that you cannot see the sealing ring. The gap between the connectors should be less than 0.5 mm.






## 7. THE CORRECT CONNECTION





Please refer to the detailed instructions of the minimum bend radius given by the cable manufacturer





# 8. DISCONNECTING THE CONNECTORS


The mated connectors can only be disconnected by using the disconnect tools.

Insert the clasp of the disconnect tool in the slots of the male connector, and the female connector will automatically get disconnected .

## **AMENDED EDITIONS AND DATES**

Rev 1.0 was released in Apr 2022 Rev 1.1 was released in Feb 2022

The technical descriptions herein are only for reference when using these products.



## LIST OF FORBIDDEN CHEMICAL SUBSTANCES





Users of T6 products should prevent the exposure of T6 products to any of the following chemical substances listed below. These chemicals may cause corrosion, degradation of performance, or cracking of product and might lead to potential safety issues in applications.

Lists of all known chemicals:

| Class  | Chemical Name  |  |
|--|--|--|
| Food release spray, Herbicide, Insecticide, Grease, Lubricate oil, Rust tors, REMA New punch oil, Stamping oil, Engine Oil, Banana Oil, WD-40 sealing agent, Doduconta B25 Kontaktol, Evabrite S, Virex TB, Suma Lin Suma Rinse, Detergent, Plasticizer, Spray cleaner8188, CM-31S, REMA oil, DX-1, CH1160, Dry lubricating oil, Paint remover, hydraulic oil, Specia quick solvent, Gasification rust inhibitor, Dehumidifying anti-rust lub Cutting oil. |  |  |
| Disinfectants/Cleaners   | Betadine, Cide, Ammonia, Organic Ammonium Chloride,<br>Hydrogen peroxide, Bleach, Saline, Detergent.   |  |
| Cosmetics  | Hand cream, Sunscreen, Lipstick, Sun screen, Makeup remover.   |  |
| Oils   | Die Cut (OELHELD), Machine Oil KV46 (Nippon Oil), Infeld stamping oil.   |  |
| Edible   | Corn oil, Cola, Light syrup, Rapeseed oil, Blend oil, Olive oil,<br>Castor oil, Soybean oil, Coconut oil.  |  |
| Acid, Alkali, Salt   | Ammonium hydrogen, Potassium hydroxide, Salt acid, Sulfuric acid, Nitric acid, Phosphoric acid, Acetic acid, Ammonia, Sodium hydroxide.  |  |
| Grease   | Vaseline, Molykote EM-50L (Dow Corning), Molykote PG-641 (Dow Corning).  |  |
| Mould Release Agent  | Pelicoat S-6 (Chukyo-Kasei).   |  |
| Binder   | Chemlok (LORD).  |  |
| Alcohols   | Ethylene glycol, Amyl alcohol, Ethanol, Isopropanol, Isopropyl alcohol (IPA).  |  |
| Fatty hydrocarbons   | Heptane, Hexane, Cyclohexane, Liquid paraffin.   |  |
| Halogenated hydrocarbon  | Freon, Carbon tetrachloride, Trichloromethane, Virex 256.  |  |
| Ketone   | Methyl Ethyl Ketone (MEK), Acetone, Methyl ethyl ketone.   |  |
| Aromatic Hydrocarbon   | Toluene, Xylene, Cresol.   |  |
| Other, Organic solvent   | Oleic acid C18H34O2, Nonanal C9H18O, Oleic acidC9H18O2, Ethyl acetate,<br>Butyl acetate, Tributyl phosphate, Kerosene, Gasoline,<br>Varnish, Esters, Ethers, Amines, Glacial acetic acid, Print ink, 3M. |  |
| Adhesion sealant   | APF125 (Wacker Chemical), 3M adhesive, Avancis adhesive.   |  |

## Remarks:

For any chemical not listed above that may come into contact with any T6 product, it is the user's responsibility to validate that such chemical will not affect the performance of T6 products.

TLIAN CO., LTD.

www.cs is olar.com